NOTE E

Small craft operators are warned to beware of severe water turbulence caused by large vessels traversing narrow waterways.

CLOONEY ISLAND

PRIEKE

Indian Bay

Marsh

Tanks

Priv aids

Dols

F G

F G

F G

10 ft rep 1990

22

28 FT JUN 2003

40 FT NOV 2009

31

Fl R 2.5s 17ft 3M "16"

Dols PA

17

F G Priv

STACK

Subm Dol

Dol

Dol

Subm Dol

RANGE "A"

Oc G 4s 34ft

R "12"

Fl R 4s 17ft 3M "10"

Fl R 6s 17ft 3M "14"

This area is foul with numerous piles and submerged piles

Fl G 4s 17ft 4M "3"

Q G 15ft

Fl R 2.5s 17ft 3M "8"

3

F G 12ft Priv

Piles

Dols

F G 12ft Priv

37 ft rep 2001

Fl R 6s 17ft 3M "6"

Platform

Platform PA

2

Fl G 4s 17ft 4M "3"

Fl R 4s 17ft 4M "4"

3

6

40 FT NOV 2009

SITE 9

210

Dol PA

G "1A"

Dol PA

3

2

Fl R 2.5s 17ft 4M "2" Ra Ref

Sign

Dols

5

Fl G 2.5s 17ft 4M "115A"

18

162 75 (see note A)

Q G 17ft 4M "117"

30"

Fl G 2.5s 17ft 4M "1"

Foul

3

Snag rep

Marker PA

Q R 17ft 4M "116"

Fl R 2.5s 17ft 4M "118"

Sign

7

6

3

10 ft rep 2009

9

(see note E)

FIXED BRIDGE
(ROSE BLUFF CUTOFF)
HOR CL 250 FT
VERT CL 135 FT

17'

SITE 11

30"

93°16' W

30°12' N

Bayou d' Inde

15

30"

14

SITE 14

12

GR
C "BD"

4

G
C "115"

13

12

Obstn

18

(see tabulation)

3 ft rep 1978

Snag

5

3

(rep 1967)

5

Spoil Area

Dols

G "1"

SITE 12

4

G "3"

4

Priv aids
G "5"

Ramp

FIXED BRIDGE
HOR CL 100 FT
VERT CL 48 FT

Snags

Subm pile

4

6

2

5

5

5

6

5

3

5

5

6

5

6

Pile

6

Snag 4

Bkw

30"

Marsh

Tree

Snag 5

Pile

6½

Pile

7 Snag

19

6

3

8

13

7

4 Pile

4

Stake

6½ Snags

7

7

16

10

6

Piling

7

5

7

6

9

4

Lock Pt

Snag

9

Pile

Piles

Snag

16

12

4

16

7

11

7

15

6

8

Dols

3

6½

30°11'03"N

93°17'33"W